

Loosen the 6 Bolts at the base of the cylinder and lift the cylinder about a half inch. (Do Not Remove cylinder)

With a putty knife, apply permatex gasket compound to top of crankcase gasket across the rear section where the gap is on the crankcase, and the top of the end cover housing on the flat surface.

This is usually where the leak is coming from.

